

ALLOCATION TABLE REPAIR KIT


SAF-HOLLAND REPAIR KITS WHEEL HUB



Fig. with exciter ring

IDENTIFICATION OF WHEEL HUB:

Laser-engraved part number
on outer ring of wheel bearing



Optional Identification:

Embossed part number of casting
(1 307 XXXX XX) in the indentations
of the wheel hub



Ø 82 mm

Repair Kit 3 434 3011 00 without exciter ring		Repair Kit 3 434 3012 00 without exciter ring		Repair Kit 3 434 3018 00 <i>INTEGRAL</i> Generation 1 with exciter ring	
Wheel Hub (complete)	Wheel Hub Casting	Wheel Hub (complete)	Wheel Hub Casting	Wheel Hub (complete)	Wheel Hub Casting
3 307 3007 00	1 301 3007 10	3 307 3006 00	1 307 3006 14	3 307 3030 01	1 307 3030 11
3 307 3008 01	1 307 3008 11	3 307 3012 00	1 307 3006 14		
3 307 3010 00	1 307 3010 10	3 307 3015 00	1 307 3015 11		
3 307 3013 00	1 307 3013 10	3 307 3016 00	1 307 3016 11		
		3 307 3017 00	1 307 3016 11		
		3 307 3022 00	1 307 3022 10		
		3 307 3024 00	1 307 3022 10		
		3 307 3025 01	1 307 3025 10		
		3 307 3026 00	1 307 3016 11		
		3 307 3029 00	1 307 3015 11		
		3 307 3033 00	1 307 3016 11		

Ø 88 mm

Repair Kit 3 434 3019 00 <i>INTEGRAL</i> with exciter ring		Repair Kit 3 434 3020 00 <i>INTEGRAL</i> with exciter ring		Repair Kit 3 434 3021 00 <i>INTEGRAL</i> with exciter ring		Repair Kit 3 434 3022 00 <i>INTEGRAL</i> without exciter ring	
Wheel Hub (complete)	Wheel Hub Casting	Wheel Hub (complete)	Wheel Hub Casting	Wheel Hub (complete)	Wheel Hub Casting	Wheel Hub (complete)	Wheel Hub Casting
3 307 3043 00	1 301 3043 10	3 307 3045 00	1 307 3045 10	3 307 3046 00	1 307 3046 10	3 307 3044 00	1 307 3043 10
3 307 3047 00	1 307 3047 10	3 307 3056 00	1 307 3056 10			3 307 3048 00	1 307 3047 10
3 307 3050 00	1 307 3050 10					3 307 3049 00	1 307 3047 10
3 307 3052 00	1 307 3052 10					3 307 3051 00	1 307 3050 10
3 307 3057 00	1 307 3047 10					3 307 3055 00	1 307 3052 10
3 307 3059 00	1 307 3047 10						
3 307 3060 00	1 307 3060 10						
	Attention! Additional information "with exciter ring" required						Attention! Additional information "without exciter ring" required



ATTENTION!

Wheel hub casting part numbers of repair kit 3 434 3022 00 are identical to repair kit 3 434 3019 00. Please check if exciter ring is mounted or not and order repair kit accordingly.

SAF-HOLLAND GmbH

Business Unit Aftermarket · Hauptstraße 26 · 63856 Bessenbach · Germany · Tel +49 6095 301-301

www.safholland.com

